GOVERNMENT OF ANDHRA PRADESH

ABSTRACT

RWS&S – S-W Monsoon Heavy Rains September 2016 – RWS Assets damaged in Guntur District – Restoration of damaged RWS Assets with an estimated cost of Rs.119.05 Lakhs under SDRF– Administrative Sanction – Accorded - Orders – Issued

---

PANCHAYAT RAJ & RURAL DEVELOPMENT (RWS-I) DEPARTMENT

G.O.RT.No. 855 Dated: 24-09-2016

Read the following:

From the Chief Engineer-I, RWS&S Dept., Hyderabad, Lr.No.AEEII(D)/DEE/ S-W Monsoon Heavy Rain Damages/Proposals/2016, Dt.24.09.2016

ORDER:-

In the circumstances reported by the Chief Engineer-I, RWS&S, AP, Hyderabad in the reference read above, Government after careful examination here by issue Administrative sanction for an amount of Rs.119.05 Lakhs (Rupees One Hundred Nineteen Lakhs and Five Thousand Only) under SDRF (State Disaster Response Fund) for 39 works towards restoration of damaged RWS assets in the South-West Monsoon Heavy Rains September-2016 in Guntur District. The list of works is appended to the order.

2. The expenditure sanctioned in Para (1) above shall be debited to the following Head of Account.

"MJH 2245	**-**	**Relief on account of Natural Calamities**
SMJH 02	**-**	**Floods, Cyclones etc.**
MJ 109	**-**	**Repairs and Restoration of Damaged Water Supply, Drainage and Sewerage works**
SH(04)	**-**	**Repairs and Restoration of damaged water supply, Drainage and Sewerage works**
270	**-**	**Minor Works**
272		**Maintanenece"**

3. The Chief Engineer-I, RWS&S, AP, Hyderabad is requested to take necessary action in the matter accordingly and submit Utilization Certificates to Government soon after completion of the works in the stipulated time.

4. This order is available on the Internet and can be accessed at http://www.goir.ap.gov.in

(BY ORDER AND IN THE NAME OF THE GOVERNER OF ANDHRA PRADESH)

Dr.K.S.JAWAHAR REDDY
PRINCIPAL SECRETARY TO GOVERNMENT (PR&RWS)

To
The Chief Engineer-I(Admin.), RWS&S, AP,Hyderabad
Copy to:-
The Commissioner for Disaster Management & E.O. Secretary to Government, A.P., Hyderbad
The Accountant General, AP, Hyderbad
The Sr.Dy.Accountant General (LABA), O/o AGAP, Hyderbad
The Director of Treasuries & Accounts, AP, Hyderabad
The OSD to Minister(PR&RWS)
The District Collector, Guntur District
The P.S. to Prl.Secy.(PR&RWS)
Sf/Sc

//FORWARDED BY ORDER//

SECTION OFFICER

ANNEXURE TO G.O.RT.NO. 855 , PR&RD(RWS.I) DEPARTMENT, DATE:24/09/2016
Restoration of RWS&S works damaged due to Heavy Rains September, 2016 in Guntur District

S.No	Mandal	Habitation	Name of the work	Damaged items	Est. Cost(Rs.in Lakhs)
1	2	3	4	5	6
1	Amaravathi	Mandepudi	Restoration of Damaged Pipe line and motor to PWS Scheme at Mandepudi	Damaged pipe lines& Motors	4.90
2	Amaravathi	Munagodu	Restoration of Damaged Pipe line and motor to PWS Scheme to Munagodu Village	Damaged pipe lines& Motors	4.00
3	Bellamkonda	Bellamkonda	Closing of SS Tank breaches of the CPWS Scheme to Bellamkonda and other habs	Pipeline Damaged	2.00
4	Chilakaluripet	Veluru	Restoration of Damaged Bunds of the SS tank of PWSS at Veluru Village	Repairs to damaged Bunds	10.00
5	Dachepalli	Gamalapadu	Restoration of Damaged pipe line at Gamalapaud CTO Office of the CPWS Sheme to Dachepalli	Pipeline Damaged	0.50
6	Dachepalli	Gamalapadu	Restoration of damaged pipe line at JP Cement Factory of the CPWS Scheme to Gamalapadu and other habs	Pipeline Damaged	0.50
7	Gurazala	Madugulla	Restoration of Damaged Pipe Line at Madugula Village of the CPWS Scheme to Gurazala and 15 other habitations	DI pipeline Damaged	6.00
8	Gurazala	Charlagudipadu	Restoration of Damaged Pipeline at Charalgudiapdu of CPWS Scheme to Gurazala and 15 other habitations	Pipeline Damaged	1.00
9	Gurazala	Gangavaram	Restoration of Damaged pipeline at Gangavaram of CPWSS to Gurazala and other habitations	Pipeline Damaged	1.00
10	Gurazala	Gurazala	Providing Motor and borewell at Srirampuram colony in Gurazala Village	Power Pump Damaged	1.50
11	Gurazala	Gurazala	Providing Motor and borewell at Venkataramanagar colony in Gurazala Village	Power Pump Damaged	1.50
12	Gurazala	Gurazala	Providing Motor and borewell at Medara colony in Gurazala Village and Mandal	Power Pump Damaged	1.50
13	Gurazala	Pulipadu	Restoration of Damaged Pipe Line at Pullipadu Village of the CPWS Scheme to Gurazala and 15 other habitations	DI pipeline Damaged	5.00
14	Krosuru	Krosuru	Restoration of damaged pipe line at Krosuru Chenchu Colony of the CPWS Scheme to Krosuru and other habs in Krosuru mandal	Pipeline Damaged	4.00
15	Krosuru	Andukuru	Restoration of damaged pipe line at Andukuru of the CPWS Scheme to Krosuru and other habs in Krosuru mandal	Pipeline Damaged	8.00
16	Krosuru	Balamarru	Restoration of damaged pipe line at Balamarru of the CPWS Scheme to Utukuru and other habs	Pipeline Damaged	5.00
17	Krosuru	Bayyavaram	Restoration of damaged pipe line at Bayyavaram of the CPWS Scheme to Utukuru and other habs	Pipeline Damaged	4.00
18	Krosuru	Utukuru	Restoration of damaged Damaged motor at Clear water sump of the CPWS Scheme to Utukuru and other habs	Motor damaged	2.00
19	Krosuru	Kastala	Restoration of motors and pipe line of the CPWS Scheme to Utukuru and other habs	Pipeline & Motors	3.00
20	Machavaram	Govindapuram	Restoration of Damaged Motors and Repairs to Pump house of the CPWS Scheme to Machavaram and 7 other habitations	Motor damaged	4.00

21	Machavaram	Kothapalem SC Colony	Providing Pipeline from Machavaram CPWSS to SC colony of Kothapalem	Existing Power Pumps blocked	2.00
22	Macherla	BKV Palem	Restoration of Damaged pedastals of pipeline at BKV Palem of CPWS Scheme to Koppunur and other habs	Pipeline and Pedastals damaged	4.00
23	Pedakurapadu	Pedakurapadu	Restoration of Damaged Pipe line and motor to PWS Scheme to Pedakurapadu	Damaged pipe lines& Motors	4.25
24	Piduguralla	Vemavaram	Closing of Breach to SS tank of PWS Scheme to Veerapuram	Breach to SS tank	10.00
25	Piduguralla	Karalapadu	Restoration of Damaged Motor to the R & R Center at Karalapadu Village	Motor damaged	1.00
26	Piduguralla	Janapadu	Restoration of Damaged Motor at Muslim Bazaar at Janapadu	Motor damaged	0.50
27	Piduguralla	PV Palem	Restoration of Damaged Pipe line at BC Colony of PWSS in PV Palem	Pipeline Damaged	2.00
28	Piduguralla	PV Palem	Restoration of Damaged Pipe line at Panditivari Veedhi of PWSS in PV Palem	Pipeline Damaged	1.90
29	Piduguralla	China Agraharam	Restoration of Damaged Pipe line at ain bazaar of PWSS in China Agraharam	Pipeline Damaged	2.00
30	Piduguralla	PV Palem	Raising of plat form of drinking water well near Cheruvu Katta in PV Palem	Platform of drinking water well	1.00
31	Prathipadu	Vangipuram	Restoration of breach to SS tank at Vangipuram Village	SS tank bund breaches at 4 places	1.00
32	Prathipadu	East palem H/o Prathipadu	Restoration of breach to SS tank at East palem H/o Prathipadu Village	SS tank bund breaches at 2 places	0.25
33	Prathipadu	Borravaripalem H/o Thikkireddypalem	Restoration of breach to SS tank at Borravaripalem H/o Thikkireddypalem Village	SS tank bund breaches at 2 places	0.25
34	Rajupalem	Kotanemalipuri & Anupalem	Restoration of Damaged Pipe line at Kotanemalipuri and Anupalem of the CPWSS to Kotanemalipuri other habs in Rajupalem mandal	Pipeline Damaged	5.00
35	Rajupalem	Srinivasa Puram & Pedanemalipuri	Restoration of Damaged Pipe line at Srinivasa Puram and Pedanemalipuri of the CPWSS to Kotanemalipuri other habs in Rajupalem mandal	Pipeline Damaged	5.00
36	Rajupalem	Bramhanpalli	Restoration of damaged pipe line in Bramhanpalli of the CPWS Scheme to Bellamkonda and other habs	Pipeline Damaged	5.00
37	Rajupalem	Chowtapayapalem	Restoration of Damaged Motors at R & R Center at Chowtapayapalem Village	Motors damaged @3 locations	3.00
38	Vatticherukuru	Pallapadu	Restoration of breach to SS tank at Pallapadu Village	SS tank bund breaches at 3 places	1.00
39	Vatticherukuru	Chintapallipadu	Restoration of breach to SS tank at Chintapallipadu Village	SS tank bund breaches at 2 places	0.50
	GRAND TOTAL ::				**119.05**

Dr.K.S.Jawahar Reddy
Principal Secretary to Government
(PR&RWS)